203 Wapoo Avenue Plan

Sam Brannan General Store-State Landmark No. 684



prepared by:

Curtis & Nicole Winslow and WTS+S, LLC 1001 Myrtle Street, Calistoga, CA 94515 (707) 341-3039, wtsasllc@gmail.com June 29th, 2010

203 Wapoo Avenue Plan

Sam Brannan General Store-State Landmark No. 684


Plan Key


- S Site Plan
- L Landscape Plan
- E Existing Floor Plan
- V NE Elevation
- W SW Elevation
- X SE Elevation
- Y NE Elevation
- Z1 Longitudanal Section
- **Z2** Transverse Section
- R Rehab Floor Plan


(Rehab Floor Plan has new legend that differs from E, and is the key to the workplans that follow).


prepared by:


Curtis & Nicole Winslow and WTS+S, LLC 1001 Myrtle Street, Calistoga, CA 94515 (707) 341-3039, wtsasllc@gmail.com June 29th, 2010














203 WAPOO AVENUE, CALISTOGA, CA 94515


APN 011-101-014-000


DRAFTSMAN: WTS+S LLC REFERENCE: 203WKESE SCALE: 1/4" = 1'0"


THE MEASURING COMPANY themeasuring company.com (415) 420-4398 WTS+S LLC CARTOGRAPHY wtsas.com (707) 333-1100

SOUTHEAST ELEVATION









THE MEASURING COMPANY themeasuring company.com (415) 420-4398

WTS+S LLC CARTOGRAPHY wtsas.com (707) 333-1100


DRAFTSMAN: WTS+S LLC REFERENCE: 203WKESE SCALE: 1/4" = 1'0"

APN 011-101-014-000

203 WAPOO AVENUE, CALISTOGA, CA 94515

TRANSVSERSE SECTION

Z2



PRIMARY RESIDENCE



STUDIO APARTMENT NO. 1



STUDIO APARTMENT NO. 2



COMMON AREAS

NOTES:

AREA NAMES HAVE CHANGED!
SEE WORK PLAN FOR DETAILS ON EACH AREA





2,126 SQ. FT. SOFT INTERIOR 1,031 SQ. FT. SOFT EXTERIOR PARCEL ~ 6,000 SQ. FT.



203 WAPOO AVENUE, CALISTOGA, CA 94515

APN 011-101-014-000

REAHB FLOOR PLAN

THE MEASURING COMPANY themeasuring company.com (415) 420-4398

WTS+S LLC CARTOGRAPHY wtsas.com (707) 333-1100

203 Wapoo Avenue Plan

Sam Brannan General Store-State Landmark No. 684

PROJECT DESCRIPTION

INTERIORS

prepared by:

Curtis & Nicole Winslow and WTS+S, LLC 1001 Myrtle Street, Calistoga, CA 94515 (707) 341-3039, wtsasllc@gmail.com June 29th, 2010

203 Wapoo Strat Preliminary Budget Jul 1st, 2010

203 Wapoo Strait Preliminary Budget Jul 1st KEY: WTSaS=e Winslow's, WF=Well Fargo	203 Wapoo Straat Preliminary Budget Jul 1st, 2010 KEY: WTSaS=_ae Winslow's, WF=Well Fargo HI=Hud Inspector	ctor					
Resource	Task	Days	Deadline	Start Date	Finish	Costs Notes	Notes
WTSaS	Conditional Use Permit	2	06/14/10	06/08/10	06/24/10	\$1,000.00	\$1,000.00 City decides cost, Execution and production costs borne by WTSaS.
WTSaS	Budget Estimates	2	06/14/10	06/08/10	06/14/10		Just time
Contractor, WF, HI	See if Contractor is on board with Bank and Jim	S	06/14/10	06/14/10	06/14/10		Have to check Monday to see if this is done. This is a commitment date
WF	Closing	9	06/19/10	06/19/10	06/29/10		Dropdead deadline for completing all pieces to this puzzle is 6/24/10.
Contractor+WTSaS	Demolition and Disposal	15	07/22/10	07/07/10		\$6,000.00	This is the key phase to determining final costs of project and general plan. WTSaS contributes labor here.
Contractor+WTSaS+HI	Assess buiding plans for budget and all code compliance	15	08/15/10	08/01/10	08/15/10		Workplan assessment milestone. All building plans are gone over with the Building Department, the Planning Department, and Napa Valley Landmarks to see best way to proceed within budget. During this time Roofing begins
Contractor+MMR	Roofing	10	08/20/10	08/01/10		\$15,000.00	\$15,000.00 Roofing takes place regardless. As this needs to be done.

203 Wapoo Str - + Preliminary Budget Jul 1st, 2010

KEY: WTSaS=___e Winslow's, WF=Well Fargo HI=Hud Inspector

Resource	Task	Days	Deadline	Start Date	Finish	Costs	Notes
Contractor+Hitmen	Termite Treatment	4	08/20/10	08/01/10		\$10,000.00	Takes place regardless, as this needs to be done. Can also be applied by contractor or contractor+WTSaS. We'll know at this point where to apply protection and where not to bother.
Contractor+WTSaS	Foam Insulation[?]	14				\$12,000.00	Foam Insulation (tigerfoam.com) SR-5 rating
Contractor+SE	Foundation					\$20,000.00	Only an estimate at this point from an educated guess. Planning on a perimeter foundation on the North Wall only.
Contractor	Wiring	7				\$15,000.00	Timetable and cost can change based on assessment milestone above.
Contractor	Plumbing	7				\$25,000.00	Timetable and cost can change based on assessment milestone above.
Contractor	Flooring	7				\$20,000.00	Timetable and cost can change based on assessment milestone above.
Contractor	Kitchen Cabinets	7				\$8,000.00	IKEA most likely. Will specify types, grades and plans
Contractor	Bathroom Fixtures	7				\$8,000.00	IKEA most likely. Will specify types , grades and plans
Contractor+WTSaS	Reframing	7				\$15,000.00	\$15,000.00 WTSaS Consulting

203 Wapoo Str t Preliminary Budget Jul 1st, 2010

KEY: WTSaS=e Winslo	KEY: WTSaS=e Winslow's, WF=Well Fargo HI=Hud Inspector	ctor)				
Resource	Task	Days	Days Deadline	Start Date	Finish	Costs Notes	Notes
Contractor+WTSaS	Floor Sanding	7				\$5,000.00	\$5,000.00 WTSaS Consulting
Contractor+WTSaS	Sheetrock	30				\$10,000.00	\$10,000.00 WTSaS Consulting
Contractor+WTSaS	Painting	20				\$6,000.00	\$6,000.00 WTSaS Consulting
Contractor+HVAC Sub	HVAC	7				\$15,000.00	\$15,000.00 Timetable and cost can change based on assessment milestone above.
Contractor	Appliances+fixtures				۰	\$30,000.00	\$30,000.00 WTSaS will specify types, plan, based on budge milestone
Contractor	Doors and Windows					\$25,000.00	\$25,000.00 WTSaS Consulting
	Total					\$246,000.00	


			are of present existing conditions.
GS-01 GS-Office (ROOM 6 on pl L: 13' 6" A: 130.50 sf W: 9' 8" P: 54.00' H: 12' 0" S: 686.50 sf		NW	NE
SW SE	NE	SE	SW
Purpose Office/Computer Room		Demolition Take down "new" pand be made depending of Carpet.	eling. Other beadboard paneling decisions to n condition of existing beadboard. Remove
Condition Originally finished with old beadboard on wal been paneled over with cheap fake wood parwall and door partitioning off the southern padoor in the half wall. Floors level, Walls plum	neling, and a half rt of the room with a	Historical Existing Beadboard or	n walls and ceilings. Like to leave if possible
Construction-Floors Sand and Varnish	Construction-Walls Sheetrock unless bea Pocket door to be ins		Construction-Ceiling Sheetrock and paint
Wiring East wall 3 quads, North 3 Quads, West 3 Quads. Dedicated Circuit for this room. Can and Fan in ceiling. Wall washers on east and west walls.	Plumbing n/a		HVAC Duct in celiling to HVAC Unit in attic.
Doors pocket door adjoining GS-02.	Windows Retrofit for now.		Finishing Paint Beadboard, Paint Sheetrock.


5000				are of present emoting conditions.
GS-02 GS	S-Bedroom (ROOM 5 or	n plan)	NW	NE
L: 10' 10" W: 8' 0" H: 12' 0"	A: 86.67 sf P: 43.33' S: 538.67 sf	_		
SW	10'-10" SE	NE.	SE	SW
<i>Purpose</i> Child's Bedroom			Demolition Take down Wall adjoir Ceiling to ceiling joists	ning GS-03. Walls stripped down to studs,
Condition Wallboard and paneling covering all interior. Floors level, Walls plumb, ceiling level			Historical Muntinned window is one framing.	of 1862 period, NE Wall is just walboard with
Construction-Floors Sand and Varnish		Construction-Walls Wall adjoining A3		Construction-Ceiling Sheetrock ceiling unless beadboard is present
and West Walls. (eceptacles each on East Can and Fan in ceiling. East and West walls. Part it	Plumbing no plumbing in this a	rea	HVAC Duct in celiling to HVAC Unit in attic.
Doors pocket doors adjo	ining GS-01 and GS-03.	Windows Historical, Retrofit/W	eatherproof/Clean	Finishing Sheetrock and Paint.

All pictures and plans displayed below are of present existing conditions.

GS-Closet (ROOM 4 on plan) **GS-03** NE NW L: 10' 10" A: 96.60 sf W: 8' 11" P: 43.33' H: 12'0" S: 570.60 sf NW SW 10 SE Demolition Purpose West wall comes down. Walls stripped down to studs, Ceiling to Walk-in Closet ceiling joists. Historical Condition Muntinned window is of 1862 Period. NE Door frame is also 1862 Wall with just fiberboard and no studs on east side. Floors level, period. Walls plumb, ceiling level Construction-Walls Construction-Ceiling Construction-Floors Sheetrock ceiling unless beadboard is Frame in New Wall on adjoining GS-02 Sand and Varnish side, approximately 8' from west wall. Wall present to be sheetrocked **HVAC** Plumbing Wiring Duct in celiling to HVAC Unit in attic. no plumbing in this area 2 AFCI Duplex Receptacles each on East and West Walls. Can and Fan in ceiling. Wall Washers on East and West walls. Part of Bedroom Circuit Finishing Windows Doors Sheetrock and Paint. Historical, Retrofit/Weatherproof/Clean pocket doors adjoining GS 02 and GS 04. Closet Shelving System


	- Company of the Comp	- 1		
GS-04 L: 11' 2 W: 11' 6 H: 12' 0	P: 44.67'		NW	NE NE
sw	11'-6"- 11'-2" 8'-5"-	NE (SE	SW
Purpose Master Bedroo				all adjoining GS-03 to be torn down. Walls s, Ceiling to ceiling joists.
Condition Floors level, Walls plumb, ceiling level			Historical Door frame opening to	EX-09 is also 1862 period.
Construction-Fl		Construction-Walls Sheetrock		Construction-Ceiling Sheetrock ceiling unless beadboard is present
and West Wal	x Receptacles each on East lls. Can and Fan in ceiling. on East and West walls. Part ircuit	Plumbing n/a		HVAC Duct in celiling to HVAC Unit in attic.
Doors Pocket Door a Door adjoining	adjoining GS-03 and Pocket g GS-05. Door	Windows Retrofit/Weatherprod	of/Clean	Finishing Paint Beadboard, Paint Sheetrock.
		1		





GS-07	GS-SE WC (WC 3 on plan)	NW	NE
L: 3' 4" W: 5' 9" H: 12' 0"	A: 19.17 sf P: 13.33' S: 237.17 sf		事	
SW	5'-9" SE	NE	SE	SW
Purpose	1		Demolition	
Will become pa	rt of GS-08.		remove toilet and sink studs, Ceiling to ceiling	remove east wall. Walls stripped down to g joists.
Condition Floors level, W	alls plumb, ceiling level		Historical n/a	,
Construction-Floo see GS-08	ors	Construction-Walls see GS-08. West and sheetrocked over.	d South doorways to be	Construction-Ceiling Sheetrock ceiling unless beadboard is present
Wiring see GS-08		Plumbing see GS-08		HVAC see GS-08
Doors see GS-08		Windows n/a		Finishing see GS-08

GS-08 G	S-SW Bath (BATH 1 on	plan)	NW	NE
L: 5'11" W: 9'8" H: 12'0"	A: 57.20 sf P: 23.67' S: 431.20 sf]		
	5'-11"		SE	SW
SW	5'-9" SE	NE		
Purpose		-	Demolition	
Main Bathroom			Remove Bathtub, Toil ceilings down to studs	et, Cabinetry and Sink. Take walls and and rafters.
Condition not in working condition. Floors level, Walls plumb, ceiling level			Historical n/a	
Construction-Floors		Construction-Walls		Construction-Ceiling
Ceramic Bathroor	m Tile	Take out east wall ac	ljoining GS-07.	Sheetrock ceiling unless beadboard is present
Wiring 4 GFCI Duplex O Bathroom Circuit because of hair d	utlets. Whirlpool Tub. (prefer dedicated circuit ryers, etc.)	Plumbing Whirlpool Tub, Two s Stall	sinks. Toilet, Shower	HVAC Duct in celiling to HVAC Unit in attic. Bathroom vent/fan through roof(?)
Doors New Door or Poc	ket Door.	Windows n/a		Finishing Sheet rock and paint.





All pictures and plans displayed below are of present existing conditions.

POB-NE Apt. 2 (ROOM 7 on plan) PO-01 NE NW A: 121.50 sf L: 13' 6" W: 9'0" P: 54.00' H: 11'0" S: 616.50 sf NW SW SE SW SE Demolition Purpose Walls stripped down to studs, Ceiling to ceiling joists. Rental Apartment Historical Condition n/a in terrible need of repair Construction-Walls Construction-Ceiling Construction-Floors Sheetrock ceiling unless beadboard is Bamboo over Concrete Slab Sheetrock present HVAC Plumbing Wiring Standalone HVAC Unit Lavatory Sink, Kitchen Sink, Toilet, Shower 2 AFCI receptacles on all walls where possible. Electric Stove, 2 GFCI receptacles in Bath and Kitchen Areas (TBD). Apt. 1 Circuit. Windows Finishing Doors Sheetrock and Paint. Retrofit Retrofit

PO-02 POB-A	pt. Hallway (HAL1	L on plan)	NW	NE
L: 8'9" W: 3'9" H: 11'0"	A: 32.81 sf P: 35.00' S: 307.81 sf			
<u> </u>		=	SE	sw
sw	8'-8" 3'-8" SE) NE		
Purpose			Demolition	
Hallway			55.57	o studs, Ceiling to ceiling joists.
Condition pretty good overall, ser	ilia wanal aanada ka ba	aradad and	Historical n/a	
replaced.				
Construction-Floors Bamboo over Concrete	Slab	Construction-Walls Sheetrock		Construction-Ceiling Sheetrock ceiling unless beadboard is present
Wiring New Electrical Panel. B Laundry/Well Room (+ Bedroom Circuit, Living Circuit, Kitchen Circuit ((subpanelled), Apt. 2 C Bathroom Circuit, Office Circuit. 1 AFCI duplex of	240) Circuit, /Dining Room (+240), Apt. 1 Circuit rcuit (subpanelled), e/Computer room	Plumbing n/a		HVAC n/a
Doors Retrofit		Windows Retrofit		Finishing Sheetrock and Paint.

PO-03	POB-SWApt. 1 (ROOM 9	on plan)	NW	NE
L: 15'5 W: 9'4" H: 11'0	P: 61.67'			
SW	9'	- NE	SE	SW
Purpose			Demolition	
Rental Studio	Apartment		Walls stripped down to	o studs, Ceiling to ceiling joists.
Condition not too bad.			Historical n/a	
Construction-Fl Bamboo over	oors Concrete Slab	Construction-Walls Sheetrock		Construction-Ceiling Sheetrock ceiling unless beadboard is present
Wiring 2 AFCI Duple:	x on each wall where possible	Plumbing Toilet, Sink, Lavatory TBD	v, Shower. Placement	HVAC Standalone HVAC Unit, Exterior
Doors Retrofit		Windows Retrofit		Finishing Sheetrock and Paint.
		21		






PO-06	POB-Kitchen Center Area	(KITCHEN on plan	n) NW	NE
L: 8'6" W: 7'6" H: 11'0'	A: 63.75 sf P: 34.00' S: 415.75 sf NW 8'-6"	NE	SE	SW
	SE			
Purpose Part of Kitchen			Demolition Walls stripped down to adjoining PO-05 and P	o studs, Ceiling to ceiling joists. Walls PO-07 to opened up as much as possible.
Condition			Historical part of NW wall is part the original arch way a	of the original exterior to the store and has and window. To be preserved and restored
Construction-Flo		Construction-Walls Sheetrock	I.	Construction-Ceiling Sheetrock ceiling
Wiring 6 GFCI Duple:	x Outlets	Plumbing See PO-05		HVAC will be open to PO-05, P0-07, GS-05 and GS-06, need range hood exhaust
Doors Retrofit		Windows Retrofit		Finishing Sheetrock and Paint. Kitchen counters and cabinets, placement TBD.

				are of present existing conditions.
PO-07 P	OB-Kitchen SE Area (PN	NTRY on plan)	NW	NE
L: 7' 2" W: 6' 0" H: 11' 0"	A: 43.00 sf P: 28.67' S: 332.67 sf			
sw	6' SE	NE	SE	SW
Purpose Part of Kitchen, a	nd maybe breakfast nook		Demolition Walls stripped down to adjoining PO-06 to op	o studs, Ceiling to ceiling joists. Wall bened up as much as possible.
Condition			Historical n/a	
Construction-Floors TBD over Concre		Construction-Walls Sheetrock		Construction-Ceiling Sheetrock ceiling unless beadboard is present
Wiring 6 GFCI Duplex O	outlets	Plumbing See PO-05		HVAC will be open to GS-05 and GS-06, need range hood exhaust
Doors Retrofit	v	Windows Retrofit		Finishing Sheetrock and Paint. Kitchen counters and cabinets, placement TBD.

		are of present existing conditions.			
PO-08	POB-Guest Bathroom (BA	ATH 2 on plan)	NW	NE	
L: 7'1" W: 5'5" H: 11'0"	A: 38.37 sf P: 28.33' S: 313.37 sf		6.16		
SW	7'-1" 5'-5"	NE	SE	SW	
Purpose			Demolition		
Guest Bathroom			Walls stripped down to studs, Ceiling to ceiling joists.		
Condition			Historical n/a		
Construction-Floors Ceramic Tile over Concrete Slab Construction-W Sheetrock		Construction-Walls Sheetrock		Construction-Ceiling Sheetrock ceiling unless beadboard is present	
Wiring 3 GFCI Duplex Outlets. Kitchen Circuit		Plumbing Toilet, Bath/Shower, Lavatory		HVAC Duct from HVAC unit in attic.	
Doors Retrofit		Windows Retrofit		Finishing Sheetrock and Paint.	



SD-01	SHED-Laundry Room (Ol	ED-Laundry Room (OFFICE on plan)		NE		
L: 20' 6" W: 7' 4" H: 8' 0"	A: 150.33 sf P: 82.00' S: 595.67 sf					
			SE	sw		
sw	20° 65	NE				
Purpose Laundry/Utility Storage Room			Demolition Take off interior wall and ceilings. Rip out plumbing and fixtures. Or tear down all together. Last option will have to be approved by Napa Valley Landmarks.			
Condition All exteriors walls rotted out, stucco covering in bad condition. Maybe we demo the whole thing.			Historical n/a			
		Construction-Walls TBD		Construction-Ceiling TBD		
Wiring 240 AC for washer and dryer		Plumbing washer and utility sink		HVAC Dryer Vent, Insulation		
Doors new door		Windows new windows		Finishing Sheetrock and Paint.		

All pictures and plans displayed below are of present existing conditions.

SHED-NW Apt. 2 (ROOM 8 on plan) **SD-02** NE NW L: 15'6" A: 131.75 sf W: 8'6" P: 62.00' H: 8'0" S: 515.75 sf NW SW SE SW NE SE Demolition Purpose Take off interior wall and ceilings. Rip out plumbing and fixtures. Rental Apartment Historical Condition n/a All exteriors walls rotted out, stucco covering in bad condition. Construction-Walls Construction-Ceiling Construction-Floors TBD Bamboo over concrete New Framing if necessary Wiring Plumbing **HVAC** Separate Heating/Cooling Unit. Insulate Toilet, Bathroom Sink, Kitchenette Sink. GFCI in Bathroom and Kitchenette. 1 walls. Duplex AFCI on each wall. Electric Range

Doors

N/A


Finishing

Sheetrock and Paint.

Windows

Retrofit

All pictures and plans displayed below are of present existing conditions.



Doors New

Windows n/a

hookup

Finishing

Sheetrock and Paint.

L=Length W=Width H=Heighth A=Floor Area in square feet (LxW) P=Perimeter in linear feet (2L+2W) S=Surface Area in square feet (2AxH)

GS=General Store c.a. 1860 PO=Porch, POB=Porch Outbbuild SD=Shed on NW, SK=Shack on NE

All pictures and plans displayed below 203 Wapoo Avenue Interior Rehab Plan are of present existing conditions. SHACK-Storage (WC 2 on plan) SK-01 NE NW A: 14.06 sf L: 2'1" W: 6'9" P: 8.33' H: 7'0" S: 137.73 sf NW SW SE SW NE SE Demolition Purpose undecided Storage or Office Historical Condition n/a Basically a wreck. Unknown if it's going to be worth doing anything with it. Construction-Ceiling Construction-Walls Construction-Floors undecided undecided undecided **HVAC** Plumbing Wiring undecided undecided undecided

Doors

undecided


Windows

undecided

Finishing

undecided

All pictures and plans displayed below are of present existing conditions.



203 Wapoo Avenue Plan

Sam Brannan General Store-State Landmark No. 684

PROJECT DESCRIPTION

EXTERIORS

prepared by:

Curtis & Nicole Winslow and WTS+S, LLC 1001 Myrtle Street, Calistoga, CA 94515 (707) 341-3039, wtsasllc@gmail.com June 29th, 2010

All pictures and plans displayed below are of present existing conditions.

EX-01 EXT-Shed Walkway 1



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D, Service Mast is bent, needs new service mast. Coordinate with PGE

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-02 EXT-Driveway



Historical n/a

Condition serviceable at this oint

Demolition no demolition intended at this time

Groundswork thd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

Notes Access to Water meter on left hand side near curb

All pictures and plans displayed below are of present existing conditions.

EXT-Apt 1 NW Walkway



Condition will be able to assess true condition after D&D Historical n/a Demolition no demolition intended at this time Groundswork tbd Wall Work tbd after D&D Wiring exterior outlet Plumbing n/a Finishing new coat of paint on wall Notes

All pictures and plans displayed below are of present existing conditions.

EX-04 EXT-Apt 1 SW Walkway



Historical n/a Condition will be able to assess true condition after D&D

Demolition take up sidewalk

Groundswork new sidewalk,

Wall Work tbd after D&D

Wiring exterior outlet

Plumbing exterior faucet

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EXT-SW Porch



Historical Restoration of window exteriors

Condition will be able to assess true condition after D&D

 $\label{eq:demolition} Demolition \ \ \text{no demolition intended at this time}$

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EXT-SW Porch Walk



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork repair of sidewalk, see ex-04

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-07 EXT-SW KItchen Walk



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork repair of sidewalk, see ex-04

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-08 EXT-SE Walkway



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork repair of sidewalk, see ex-04

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EXT-SE Porch



Historical Restoration of door, column decoration and window exteriors

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-10 EXT-SE Porch Walkway



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-11 EXT-SE Path



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-12 EXT-NE Shack Wall



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EXT-NW Shack Wall



Historical n/a Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D


Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-14 EXT-Shack NW Wall



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-15 EXT-PO-09 Wall



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EXT-GS-04 Wall



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-17 EXT-GS-03 Wall



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below 203 Wapoo Avenue Exterior Rehab Plan are of present existing conditions. EX-18 EXT-GS-02 Wall Historical n/a Condition will be able to assess true condition after D&D Demolition no demolition intended at this time Groundswork tbd Wall Work tbd after D&D Wiring n/a Plumbing n/a Finishing new coat of paint on wall Notes

All pictures and plans displayed below are of present existing conditions.

EXT-GS-01 Wall



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EXT-PO-01 Wall



Historical n/a

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EXT SD-01/SD-02 NW Wall



Historical Victorian Era, possible grant for restoration, getting quotes

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-22 EXT-Wrought Iron Fence NE



Historical Victorian Era, possible grant for restoration, getting quotes

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork thd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

All pictures and plans displayed below are of present existing conditions.

EX-22 EXT-Wrought Iron Fence SE



Historical Victorian Era, possible grant for restoration, getting quotes

Condition will be able to assess true condition after D&D

Demolition no demolition intended at this time

Groundswork tbd

Wall Work tbd after D&D

Wiring n/a

Plumbing n/a

Finishing new coat of paint on wall

	203 Wapoo Av	venue Exterior Rehab Plan	All pictures and plans displayed below are of present existing conditions.
	RO-01 RO	OF-Gabled	
rg 1			
	Historical	n/a	Condition At the end of it's useful lifespan and needs to be
		.,,	Condition At the end of it's useful lifespan and needs to be replaced
	Demolition	no demolition intended at this time	
(_)	Groundswork	n/a	
	TA7 - 11 TA71 -		
	vv ali vv ork	NEW ROOF	
	Wiring	n/a	
	Plumbing	n/a	
11			
	Finishing	NEW ROOF	Notes
2 f _ h			

	203 Wapoo Avenue Exterior Rehab Plan		All pictures and plans displayed below are of present existing conditions.	
	RO-02 RO	OF-Porch Hip		
)				
	Historical	n/a	Condition At the end of it's useful lifespan and needs to be replaced	
	Demolition	no demolition intended at this time		
(<u>-</u>)	C11.			
	Groundswork	n/a		
	Wall Work	NEW ROOF		
	Wiring	n/a		
		II/a		
	Plumbing	n/a		
	Finishing	NEW ROOF	Notes	
	0			

203 Wapoo	Avenue Exterior Rehab Plan	All pictures and plans displayed below are of present existing conditions.
RO-03 F	ROOF-Shed	
Histori	cal n/a fon no demolition intended at this time	Condition At the end of it's useful lifespan and needs to be replaced
Groundswo		
	ing n/a	
	ing n/a	
Finish	ing NEW ROOF	Notes

203 Wapoo Av	venue Exterior Rehab Plan	All pictures and plans displayed below are of present existing conditions.
RO-04 RO	OF-Shack	
Historical	n/a	Condition At the end of it's useful lifespan and needs to be replaced
Demolition	no demolition intended at this time	
C11.		
 Groundswork	n/a	
Wall Work	NEW ROOF	
Wiring	n/a	
Plumbing	n/a	
Finishing	NEW ROOF	Notes