



CORRUGATED METAL ROOFING



SURFACE TRACK SLIDING DOORS WITH COPPER LIGHT ABOVE



DOOR OVERHANG DETAIL WITH COPPER ROOF GUTTERS & DOWNSPOUTS



STAINED VERTICAL WOOD SIDING



PHOTOGRAPH AT THE EXISTING FRONT ENTRY. EXTERIOR FINISHES AT ADDITION TO MATCH CURRENT MATERIALS.



SYAR STONE LANDSCAPE WALLS

AUBERT WINERY ADDITION



METAL ENTRY DOOR & WINDOWS