

345 Silverado Trail – Photo Exhibit



Photo 1 &2: Entrance gate & storage shed on (E) concrete slab



Photo 3: Propane tank & entrance gate – Gate with open flame toppers



Photo 4: Light poles on either side of access road



Photo 5: Slope to Mt. Washington access road



Photo 6: Tree stump on slope to Mt. Washington access road



Photo 7: Large foundation/slabs – Red Tagged



Photo 8: Metal building adjacent to pond



Photo 9: Peacock aviary adjacent to pond



Photo 10: Aviary harboring peacocks, ducks, & possibly other bird species



Photo 11: Inside peacock aviary



Photo 12: Non-operational helicopter “sculpture”